

Pre Delivery Inspection Report

Job No: MWJ138311



CUSTOMER COPY

















Booking Date: 01 Jan 2021

Customer Name:



REED AUTOS 1.0L Petrol 2020
Mileage:

ROAD TEST

Check	Result
1 Engine Starts and Idles Properly	Green  
2 Engine Noise Normal (Cold/Hot & High/Low Speeds)	Green  
3 Auto/Manual Transmission Operation Noise Normal Cold/Hot	Green  
4 Clutch Operates Properly	Green  
5 Steers Normally (Response Centring and Free Play (Tracking))	Green  
6 Body and Suspension (No Squeaks or Rattles)	Green  
7 Brakes/ABS Operates Properly	Green  
8 Instrument Cluster Operates Properly	Green  

DOORS, WINDOWS AND LOCKS

Check	Result
9 All Window Switches are Operational	Green  
10 Windows Operate Correctly	Green  
11 All Doors Open Inside & Out	Green  
12 Door Locks Operate Correctly	Green  
13 Keys and Remotes	Green  

SEATS

Check	Result
14 Front Seat Adjusters	Green  
15 Folding Rear Seats	Green  
16 Rips or Tears	Green  

MIRRORS, SCREENS & BODYWORK

Check	Result
17 Fuel Flap	Green  
18 Side Wing Mirror Operation	Green  
19 Rear View Mirror	Green  

20	Window Screen	Green	●
21	Rear Screen	Green	●
22	General Exterior Condition	Green	●
23	Tyre Tread Depths	N/S/F (MM): 8 , O/S/F (MM): 8 , N/S/R (MM): 8 , O/S/R (MM): 8	●

TOOLS

Check	Result
24 Tool Kit	Green ●
25 Spare Wheel Space Saver or Tyre Sealant	Green ●
26 Locking Wheel Nut	Green ●

AUDIO SYSTEMS

Check	Result
27 Radio	Green ●
28 Radio Antenna	Green ●
29 CD	Green ●
30 Speakers	Green ●
31 Phone System & Bluetooth	Green ●

HEATERS/VENTS/A/C/DEFOG

Check	Result
32 Air Conditioning System	Green ●
33 Heating System	Green ●
34 Defog/Defrost	Green ●

INTERIOR FACILITIES

Check	Result
35 Sun Visors + Mirrors	Green ●
36 Steering Column Lock	Green ●
37 Steering Wheel Controls	Green ●
38 Instrument Panel and Warning Lights	Green ●
39 Washer/Wipers	Green ●
40 Power Outlets and Lighters	Green ●
41 Centre Consoles and Gloveboxes	Green ●
42 Parcel and Luggage Shelves	Green ●
43 General Interior Condition	Green ●


OPTIONAL EXTRAS AND MISCELLANEOUS

Check	Result
44 Parking Sensors	Green 
45 Rear View / Surround Cameras	Green 
46 Navigation System	Green 
47 Sunroof / Convertible Top	Green 
48 Cruise Control	Green 
49 Start Stop Operation	Green 
50 Heated/Cooled Seats	Green 

AIR BAGS & SAFETY BELTS

Check	Result
51 Airbags	Green 
52 Seatbelts	Green 

BRAKES

Check	Result
53 Visual Check including Calipers, Pads, Shoes, Discs, Drums, Brake lines, Hoses and Fittings OSF	Green 
54 Visual Check including Calipers, Pads, Shoes, Discs, Drums, Brake lines, Hoses and Fittings NSF	Green 
55 Visual Check including Calipers, Pads, Shoes, Discs, Drums, Brake lines, Hoses and Fittings OSR	Green 
56 Visual Check including Calipers, Pads, Shoes, Discs, Drums, Brake lines, Hoses and Fittings NSR	Green 
57 Parking Brake	Green 
58 Master Cylinder and Server	Green 

COOLING SYSTEM

Check	Result
59 Coolant Check	Green 

ELECTRICAL SYSTEM

Check	Result
60 Starter Operation	Green 
61 Battery	Green 
62 Alternator Output	Green 

FLUIDS AND COOLANTS

Check	Result
63 Engine Oil	Green 

64	Coolant	Green	●
65	Brake Fluid	Green	●
66	Power Steering Fluid	Green	●
67	Washer Fluid	Green	●

ENGINE

Check	Result
68 Fluid Leaks	Green ●
69 Hose and Fixings	Green ●
70 Aux Belts	Green ●
71 Wiring	Green ●
72 Engine Mounts	Green ●

EXHAUST SYSTEM

Check	Result
73 Visual Check Exhaust System Condition	Green ●
74 Emissions Test	Green ●

FUEL SYSTEM

Check	Result
75 Fuel Pump Noise Normal	Green ●
76 Fuel Filter	Green ●
















FRAME

Check	Result
77 Visual Frame Inspection	Green ●

LIGHT SYSTEM

Check	Result
78 Front Headlights	Green ●
79 Front Sidelights	Green ●
80 Front Full Beam	Green ●
81 Front Indicators	Green ●
82 Rear Main Lights	Green ●
83 Rear Side Lights	Green ●
84 Rear Brake Lights	Green ●
85 Rear Reverse Light	Green ●
86 Rear Fog Lights	Green ●

TYRES WHEELS AND SUSPENSION

Check	Result
87 Tyres Sizes Are Correct Across the Same Axle	Green 
88 NSF Tyre tread depth and PSI	MM: 8 , PSI: 32 
89 NSR Tyre tread depth and PSI	MM: 8 , PSI: 32 
90 OSR Tyre tread depth and PSI	MM: 8 , PSI: 32 
91 OSF Tyre tread depth and PSI	MM: 8 , PSI: 32 
92 Tyre Pressure Monitoring System	Green 
93 Wheel Covers and Centre Caps	Green 
94 Alloy Wheels Condition	Green 
95 Rack and Pinion Linkage and Boots	Green 
96 Control Arms/Bushings and Ball Joints	Green 
97 Tie Rods and Idler Arms	Green 
98 Sway Bar Links and Bushings	Green 
99 Springs	Green 
100 Struts and Shocks	Green 
101 Power Steering Pump	Green 

TECHNICIAN

Check	Result
102 Checked By	REED AUTOS LTD 